

TD - Engineering Fabrication Component Kit List

Process Engineering

Component Serial No. PIPPS003

Kit submitted by: D.Bice

Fermi ID No. 12413

Date submitted: 19-Oct-12

Need date: 19-Oct-12

Deliver to: P/U

Use with Traveler No. 464029

Job No.

M&S task number: 18.13.7.4.3.2.6.2

Drawing Title: 1.3 Ghz Single Cell Vertical Test

Drawing No. MB-443595 Rev None

Material Control

Parts available

Verified by: Marsha Schmidt MS

Fermi ID No. 4223

Date submitted to stockroom: 10/19/2012

Parts issued

Issued by:

Fermi ID No.

Date issued:

Parts received by E&F: *[Signature]*

Fermi ID No. 12413

Date received by E&F: 10-19-12

	Description	Dwg Size	Number	Rev	Unit	Quantity Required	Location	Quantity Issued	E&F Verified	Routing Form Number	Spares Number / Comment
1	2-3/4" Conflat copper gasket	MA	393931	A	ea	4	BS CAB	4		94836	64 pcs. MDC#191-006
2	Nut M8 SB	MA	393924		ea	CPL has		—		—	
3	Nut M6 SB	MA	393925		ea	CPL has		—		—	
4	Studs M8 70mm lg	MA	393926		ea	CPL has		—		—	
5	Studs M6 40mm lg	MA	393927		ea	CPL has		—		—	
6	SHCS M4 20mm lg	MA	393929		ea	CPL has		—		—	
7	Mini conflat copper gasket	MA	393930		ea	2	BS CAB	2		92870	59 pcs. MDC#191-000
8	Burst disk	MA	393932		ea	CPL has		—		—	Ref#BDA-M part#420030
9	Right angle valve	MA	393933		ea	CPL has		—		—	VAT 54032-GE02-0002/6039
10	Washer M8 od:15.50mm	MA	393934		ea	CPL has		—		—	
11	Washer M6 od:11.50mm	MA	393935		ea	CPL has		—		—	

TD - Engineering Fabrication Component Kit List

	Description	Dwg Size	Number	Rev	Unit	Quantity Required	Location	Quantity Issued	E&F Verified	Routing Form Number	Spares Number / Comment
12	Washer M4 od:8mm	MA	393936		ea	CPL has		<u> </u>		<u> </u>	
13	Conflat blank-off flange	MA	393937		ea	CPL has		<u> </u>		<u> </u>	S-38: 3020-126000
14	Reducing tee for burst disk	MA	393947		ea	CPL has		<u> </u>		<u> </u>	MDC PN#404044
15	Beampipe flange seal	MB	439232	B	ea	4	BS CAB	4		93917	978 pcs.
16	Mod. top beamline flange Assy.	MB	457080		ea	CPL has		<u> </u>		<u> </u>	
17	Mod. bottom beamline flange Assy.	MC	457718		ea	CPL has		<u> </u>		<u> </u>	
18	Input Coupler Assembly	MC	457838		ea	CPL has		<u> </u>		<u> </u>	
19	Field Probe	MC	457873		ea	CPL has		<u> </u>		<u> </u>	
20	Silicon Bronze nut plate, Halves	MB	459093		pair	CPL has		<u> </u>		<u> </u>	4 halves equal 2 pair